

General instructions on packaging and labeling

Goods tag

Update: February 2007




Goods tag

Products and shipping units must be identified through clear and systematic marking. In principle, packing units are labelled with standardised labels with readable barcode. SupplyOn provides VDA 4902 Version 4 as standard.

Each package and, if necessary, the container (when bundled together, every individual container) must display a label.

The type of label chosen must remain legible to the human eye and for automatic scanning at point of delivery, withstanding environmental and transport conditions. All labels are barcoded and if necessary adhesive, according to the transporting container. Any deviations are to be agreed with the relevant MANN+HUMMEL plants. If labels are missing, illegible or incomplete, MANN+HUMMEL reserves the right to charge the supplier with any additional costs incurred. This also applies to additional costs incurred through non-removal of old labels, incorrect attachment or other irregularities.


Example of labeling



Goods tag Page 2



Example of container label



Example of label for packaging unit, e.g. small box



Goods tag Page 3